

Software Release Notes

dSS V1.11.2.1

The digitalSTROM AG uses Software Release Notes (SRN) to provide information about software changes and updates of existing products.

| | |
|-----------------|-------------------|
| Document-Number | SRN-1605 |
| Date/Version | 19.05.2016 / v1.0 |

Important: when updating from version 1.10.3, the update dialog will not close automatically. Therefore, the Configurator must be reloaded manually latest 30 minutes after the update started.

Improvements

- Some User Defined Actions might neither been displayed nor executed after updating to release 1.11.2. This problem was solved.
- A problem within the Event-Responder app was solved. The issue was a trigger on a device push-button action that could not be saved.

Software Update Recommendation

Updating to this software-version is strongly recommended to benefit from the latest improvements.

Documentation

Further information about the features and how to use them can be found in the latest digitalSTROM manual under "Operation and Configuration" or "Installation".

The latest version of the manuals can be found on

<http://www.digitalstrom.com/en/Partner/Support/Operating-manuals/>.

Affected Products

| Product | Software Description | New Version | Where to find the version info | Release date |
|-------------------------------------|----------------------|-------------|-----------------------------------|--------------|
| digitalSTROM-Server dSS11 / dSS11-E | dSS Version | 1.11.2.1 | In the dS Configurator (Figure 1) | 19.05.2016 |

Installation Notes

- Execute the software update from the digitalSTROM configurator within the menu "*System / System Update*".
- The dSS must be connected to the Internet in order to perform the update. Alternatively, the update can be installed by using a USB thumb drive.
- It is advisable to back up your system settings prior to performing a system update within the menu "*System / System Maintenance*".
- Once the system updates are installed, the system again checks for available updates. In case there are additional dSM firmware updates available, they must be installed manually by clicking the "*Update dSM firmware*" button.
- Please note that the server-apps must be updated separately from the menu "*Apps / Update*".
- A complete list of release notes as well as the USB update file can be found at <http://www.digitalstrom.com/Partner/Support/Software-Updates/>.

How to find the version information

The currently installed software version can be found within the digitalSTROM Configurator.

Apps Aktivitäten Räume Gruppen System **Hardware** Hilfe

Meter

| Status | Name | dSM ID | Anzahl Geräte | Neue Geräte Sperren | Leistung (...) | ARM Soft. | DSP Soft. | HW Version |
|--------|-----------------------------|----------|---------------|---------------------|----------------|-----------|-----------|------------|
| ● | F1 EG Wohnraum Küche | 00000671 | 9 | deaktiviert | 2 | 1.16.0.0 | 1.4.1.0 | 17.1.2.16 |
| ● | F1 EG Korridor Schlafzimmer | 00000713 | 10 | aktiviert | 2 | 1.16.0.0 | 1.4.1.0 | 11.1.21.0 |

Geräte **dSM-Software Version: ARM DSP**

| Name | dSID | Ausgang | Eingangs Modus | Eingang | Raum Name | Rau... | HW Info | Firm... | Regist... | Inaktiv... | ... |
|---------------------|----------|-------------|----------------|---------|--------------|--------|-----------|---------|------------|------------|-----|
| Deckenleuchte | 0001890c | gedimmt | | | Schlafzimmer | 2 | GE-KM200 | 3.1.7 | 9 11:50:39 | | |
| Taster Schlafzim... | 000064f6 | deaktiviert | | | Schlafzimmer | 2 | GE-TKM210 | 3.1.4 | 9 11:48:36 | | |
| Paniktaster | 00009abb | deaktiviert | Panik | | Wohnraum | 4 | RT-TKM200 | 3.1.5 | 9 11:49:43 | | |
| Jalousie | 00016c22 | | | | Schlafzimmer | 2 | GR-KL200 | 3.2.1 | 9 11:48:42 | | |

1.8.0 **dSS Version** Ansicht aktualisieren Standard Ansicht Deutsch

Fig. 1: Version number for dSS and dSM